

U. S. Department of Agriculture
FOREST SERVICE

N-17

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 143 R. 26 Mer.


Sec Corner common to Sections
14, 15, 22, and 23

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Balsam _____

Diameter 12 _____

Bearing S10W _____

Distance 6.44 _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

G. Sherman

(Signature)

Engineer

(Title)

3/7/35
(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

4

from which this Corner bears South

side of trees
tree 8 inches diameter, on the North

Metal Location Poster is on a Pop. (Aspen)



(Make sketch of topography near Corner)

N-17 Mer.

R-26

T-143