

A1

U. S. Department of Agriculture

FOREST SERVICE

A-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 1434144 R. 27+28 5th Mer.

Sec. Corner common to Sections

1, 6, 31, and 36

Corner consists of a Iron Pipe ~~(rod)~~ in place


State condition Good

Dimensions above ground 24" high inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species T.M. T.M. T.M.

Diameter 6" 6" 6"

Bearing N. S 85° E S 40° E

Distance .25 .10 .26

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl H. Handy

(Signature)

Chief of Party

(Title)

(Date)

A1

Corner again.

Give any further facts which will aid in finding this

chains distant.

25


from which this Corner bears *South*

side of *Said Tree*

tree *6*" inches diameter, on the *South*

T.M.

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 144 N. R. 27 E. 28

574

MAR 1

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

1216-25
 123

Chippewa NATIONAL FOREST

PA-1

CORNERS OF THE PUBLIC SURVEY

T. 14YN/43N R. 27+28W - 5th Mer.

SEC. COR. Corner common to Sections
36, 31, 1, and 6 -


Corner consists of a 1000 Pipe (set) in place
 State condition Good.

Dimensions above ground 24" high inches.


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species	<u>Tam.</u>	<u>Tam.</u>	<u>Tam.</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>N.</u>	<u>S85E</u>	<u>S40E</u>	_____
Distance	<u>.25</u>	<u>.10</u>	<u>.26</u>	_____

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? _____

 (Signature)
Earl W. Handy
 (Title)
Chief of Party

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


25

from which this Corner bears South-

side of said tree

tree 6" inches diameter, on the South

Metal Location Poster is on a Tam



(Make sketch of topography near Corner)

T. LYNN R. 27428 W. 5th Mer.