

U. S. Department of Agriculture

FOREST SERVICE

A-5
11-16-25
123

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 & 143 N. R. 27 W. 5th Mer.

Section 7 Corner common to Sections 31, 32, 5, and 6

Corner consists of a No Stake (not) in place State condition

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T143N
R27W-
S. 5-

--

--

--

B.T.

--

--

--

Species N. Pine

Diameter 1.8" D.B.H.

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Earl M. Handy


(Signature)

Chief of Party

(Date)

(Title)

A-5



(Make sketch of topography near Corner)

Metal Location Poster is on a

tree 8" inches diameter, on the NW

side of Solid tree

from which this Corner bears

N 9 W

chains distant.

Give any further facts which will aid in finding this

Corner again.

B.T. lying flat on ground -
scribing on bottom -

T. 144+13 N R. 27 W

Sta. A-5 Mer.