

Z-7

U. S. Department of Agriculture

P.

FOREST SERVICE

Z-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 27W 5P Mer.

Meander Corner common to Sections 32, 5, and

Corner consists of a Iron post (not) in place State condition Good

Dimensions above ground 14 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

161 General Land Office Survey							
T 143N R 27W							
Sec 32 / MC							
Sec 5							
T 143N R 27W							

N W E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

3/25/35 Robert Berube (Signature) Estimator (Title)

(Date)

Z-7


Handwritten notes on the top section of the page, including the number '7-5' in the upper left corner.

Corner again.
Along Lake shore

Give any further facts which will aid in finding this chains distant.

side of *60*
from which this Corner bears *S 87° W*

tree *8* inches diameter, on the *N*
Metal Location Poster is on a *newly clearing*



(Make sketch of topography near Corner)