

Z-11

U. S. Department of Agriculture
FOREST SERVICE

Z-11

Z-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14³ R. 28 Mer.

$\frac{1}{4}$ Corner common to Sections
33, and 4



Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.



Species Elm _____

Diameter 10" _____

Bearing South _____

Distance 406 _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

C Sherman

(Signature)

Engineer

(Title)

3/13/25

(Date)

Z-N

Corner again.

Give any further facts which will aid in finding this


..... chains distant. **3**

from which this Corner bears **EAST**

side of **Type**

tree **10** inches diameter, on the **WEST**

Metal Location Poster is on a **E/M**



(Make sketch of topography near Corner)