

U. S. Department of Agriculture  
FOREST SERVICE

A-16  
A-16

*Chippewa*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 27 5th Mer.

1/4 Corner common to Sections  
3, \_\_\_\_\_, and \_\_\_\_\_



Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box  
and fill blanks below, giving bearings from Corner to Trees  
and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence


*Stanley M. Morrison*  
(Signature)

3/24/60  
(Date)

*Stanley M. Morrison*  
(Title)

A-16

T. 193 R. 27  
 52  
 A-16  
 MER.



Metal Location Poster is on a *Red Pine* tree 8 inches diameter, on the *East* side of *Tree* from which

this Corner bears \_\_\_\_\_ (Bearing) \_\_\_\_\_ (Distance) Chains.

Section line marker between Secs. \_\_\_\_\_ and \_\_\_\_\_ is on

a \_\_\_\_\_ on the \_\_\_\_\_ (Tree, post, etc.)

located \_\_\_\_\_ chains *N., N. & S., from Sec. Cor.; 1/2 Cor.; Witness Cor.*

(Cross out nonapplicable)

Give any further facts needed to find Corner again:

*Blk. Prof. F. & W. of*

*Corner.*