

U. S. Department of Agriculture

FOREST SERVICE

T-1 P.
~~5-5~~

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N R. 28 W 5 Mer.

Corner common to Sections 25, 30, and

Corner consists of a post (not) in place State condition good

Dimensions above ground 12 inches Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

91.5 General Land Office Survey							
25	25	30	30				
N	W	S	E	NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

No B.T.s			

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

3/29/35 (Date) M. Purcell (Signature) Estimator (Title)

Corner again:

Give any further facts which will aid in finding this

~~...obtain distant~~

~~from which this corner bears~~


St. Louis

side of

tree—3 inches diameter, on the

Metal Location Poster is on a

St. Louis State



(Make sketch of topography near corner)

Mer. T-1

5

R. 25 W

43 N