

U. S. Department of Agriculture  
FOREST SERVICE

2-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 28 Mer.

1/4 Corner common to Sections 34 and 3



Corner consists of a (not) in place State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm

Diameter 28"

Bearing N45W

Distance 118.4

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. Sherman

(Signature)

Engineer


(Title)

3/13/22

(Date)

Corner again.

Metal Location Poster is on a ELM  
 tree 28 inches diameter, on the SW  
 side of TRC  
 from which this Corner bears 118 L -  
 chains distant. - Bearing TRC  
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

2-15

Mer.

T. 143 R. 28