

U. S. Department of Agriculture

FOREST SERVICE

W
6-18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 28 5th Mer.

1/14

Corner common to Sections

-----, 11, and -----

Corner consists of a iron pipe (set) in place


State condition good

Dimensions above ground 1" x 12" high inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? no evidence


Stanley M. Morrison
(Signature)

Forestry and
(Title)

2-1-61
(Date)

T. 143 R. 22 S. 2 Mer. 5-18

(Make sketch of topography near Corner and show section line markers with "X")



Metal Location Poster is on a *Horse* tree *6* inches diameter, on the *line* side of *line* from which this Corner bears *SE*, *4 ft* (Bearing) and (Distance) is on Section line marker between Secs. *and* on the (Tree, post, etc.) (Name of road, trail, etc.) located chains *L. W. N. R.* from Sec (or; $\frac{1}{2}$ Cor.; $\frac{1}{4}$ Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: *Blue line marked N. 2 E of log*

