

U. S. Department of Agriculture
FOREST SERVICE

W

6-19

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ~~145~~ 143 R. 28 Mer. 52

74

Corner common to Sections

_____, 11, and _____

Corner consists of a metal tag (not) in place


State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS




N W S E

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *No evidence*


Stanley M. Marvin
(Signature)

2-1-61
(Date)

(Title)

T. 143 R. 28 Mer. 6-9
 5 A

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a blm
 tree 5 inches diameter, on the west
 side of the
 this Corner bears _____
 (Bearing) _____
 (Distance) _____
 is on _____ and _____
 Section line marker between Secs. _____
 a _____ on the _____
 (Tree, post, etc.) _____
 (Name of road, trail, etc.) _____
 located _____
 chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor.
 (Cross out nonapplicable)
 Give any further facts needed to find Corner again:
Blue line poster N. 20
of corner