

U. S. Department of Agriculture

FOREST SERVICE

A-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 & 144 R. 28 5th Mer.

Corner common to Sections 1, and 36


Corner consists of a (not) in place State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Oak

Diameter 5" D.B.H.

Bearing S. 49 W

Distance 30 ft.

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why?

Carl W. Handy (Signature)

Chief of Party (Title)

(Date)

Corner again.

Give any further facts which will aid in finding this


45 chains distant.

from which this Corner bears N 49 E

side of SOLD TREE

tree inches diameter, on the N.E.

Metal Location Poster is on a Oak



(Make sketch of topography near Corner)

A-23

Mer.

5 1/4

T. 143 N. R. 28