

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

T, 4 ~~1~~^P

CORNERS OF THE PUBLIC SURVEY

T. 1431X R. 2 SW 3 Mer.

M C

Corner common to Sections

25, 30, and

Corner consists of a *Iron nail* (not) in place

State condition

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

U.S. General Land Office Survey

<i>M C</i>				<i>U.S. General Land Office Survey</i>			
<i>S 25</i>		<i>S 30</i>					
N	W	S	E	NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Robert Carver
Estimator
 3/29/13
 (Date) (Title)

UNITED STATES GEOLOGICAL SURVEY

REPORT OF THE FIELD SURVEY

John Stone

Corner again.

Give any further facts which will aid in finding this

chain distant.

1.40

from which this Corner bears

S. 5 W.


side of

stone

tree 3 inches diameter, on the

Metal Location Poster is on a

John Stone



(Make sketch of topography near Corner)

T-4-1

Mer.

R. 28 W.

T. 14 N.