

U. S. Department of Agriculture

FOREST SERVICE

V, W-9 P.

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 28W 5 Mer.

Meander Corner common to Sections

32, 33, and

Corner consists of a Gov's Iron Bolt (not) in place



State condition Good

Dimensions above ground 16 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Bass B. Ash

Diameter 8 8

Bearing S35<sup>o</sup>E S33<sup>o</sup>W

Distance 0.24 0.21

Do you believe this to be a genuine Land Office Corner?

If not, why? \_\_\_\_\_

Robert Purcell

4/5/35

Estimator

(Date)

(Title)

*North of road  
along of corner*

Corner again.

Give any further facts which will aid in finding this

chain distant.


from which this Corner bears *0.00*

*S 70.0 E*

side of

tree 5 inches diameter, on the

Metal Location Poster is on a *corner*



(Make sketch of topography near Corner)

*M-9*

*T. L. ... R. 28 W*