

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 29W 5 Mer.


Section Corner common to Sections
23, 24, 25, and 26

Corner consists of a Center of Road (not) in place
State condition Not Visible

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Maurice Schaller

(Signature)

Estimator

(Title)

3/29/35
(Date)

Board East + West

Corner again.

Give any further facts which will aid in finding this


by linking chains distant.

from which this Corner bears N 15° E

side of Tree

tree B. Inches diameter, on the North

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)