

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

V-23

P.

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 29W 3 Mer.

Corner common to Sections

25, 26, 35, and

Corner consists of a Small iron pipe in place

State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 25		S 36	
---------	--	---------	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<u>None</u>		

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

4/11/35 Robert Beers
 (Date) (Signature)
Estimator
 (Title)

V-23

Corner again.
 On east side
 of road back
 of property

Give any further facts which will aid in finding this

chains distant.

0.47

from which this Corner bears

S 35.5 E

side of

the

tree 12 inches diameter, on the

Metal Location Poster is on a

H. M. ...

