

U. S. Department of Agriculture

FOREST SERVICE

K-1
K1

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY


T. 143N R. 30W+31W 5th Mer. Sixteenth Corner common to Sections

12, and 18
Corner consists of a Br. cap. iron pipe (not) in place
State condition good

Dimensions above ground 1 x 7 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine W. Oak
Diameter 14 14
Bearing S 67° 15' E N 86° W
Distance 40 100

Do you believe this to be a genuine Land Office Corner? Yes
If not, why?

Dorman J. Sutton
(Signature)

12-11-34
(Date)

Compassman
(Title)

Corner again.

Give any further facts which will aid in finding this


140 chains distant.

from which this Corner bears N 67° 15' E

side of tree

tree 14 inches diameter, on the NW

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T. 145N R. 30 + 51W B + 11 Mer. K-1