

U. S. Department of Agriculture

FOREST SERVICE

Posted K2

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 30 W. 5th Mer.Sixteenth Corner common to Sections
18, _____, and _____Corner consists of a Brcap iron pipe in place
State condition goodDimensions above ground 1x11 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species W. Oak W. OakDiameter 12 19Bearing N10°15'WDistance 23Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Dorman J. Sutton

(Signature)

12-10-34
(Date)Compassman
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears $S 10^{\circ} 15' E$

side of trees

tree 12 inches diameter, on the S E

Metal Location Poster is on a W. Oak



(Make sketch of topography near Corner)

K-2 Mer.

5th

R. 30

T. 143N