

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

G2

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 30W 5th Mer. Sixteenth Corner common to Sections

7, , , and



Corner consists of a 3/4" cap iron pipe (not) in place State condition good

Dimensions above ground 1.87 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen - ~~Stub~~ Aspen - Stub

Diameter 10"

Bearing S35° E N73° W

Distance 13 5

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dorman J. Sutton (Signature)

12-12-34 (Date)


Compassman (Title)

Corner again.  
Give any further facts which will aid in finding this

13 chains distant.

from which this Corner bears N 35° W  
side of trees.

Metal Location Poster is on a Aspen tree 10 inches diameter, on the N W



(Make sketch of topography near Corner)

T. 143 N R. 30 W 5th Mer. G-2