

U. S. Department of Agriculture

FOREST SERVICE

*Posted*

63

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143N* R. *30W* *5<sup>th</sup>* Mer. Quarter Corner common to Sections

*7*, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a *Br cap iron pipe* (not) in place



State condition *good*

Dimensions above ground *1.18* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>C 1/4</i>	<i>Grown</i>		
<i>ST</i>	<i>over</i>		
<i>B.T.</i>	<i>B.T.</i>		

Species *N. Pine* *R. Oak*

Diameter *10* *6*

Bearing *N 7° W* *S 89° E*

Distance *30* *12 1/2*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*Dorman J. Sutton*

(Signature)

*Compassman*

(Title)

*12-11-34*

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant. 185

from which this Corner bears N 89° W

side of trees

tree 6 inches diameter, on the N.W.

Metal Location Poster is on a R. Oak



(Make sketch of topography near Corner)

T. HAN R. 30W 5th Mer. G-3