

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 30 W. 5<sup>th</sup> Mer.

Sixteenth Corner common to Sections 6, and


Corner consists of a Brass iron (not) in place State condition good

Dimensions above ground 1x5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species R. Oak

Diameter 13

Bearing S. 67.90 E

Distance 36

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dorman J. Sutton (Signature)

Compassman (Title)

1-3-36 (Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *N 67° 30' W*

side of *tree*

tree *13* inches diameter, on the *NW*

Metal Location Poster is on a *Rock*



(Make sketch of topography near Corner)

*T. 113N R. 30W 5th D-3 Mer.*