

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N R. 30 W 5th Mer.

Sixteenth Corner common to Sections 6, and 7



Corner consists of a 1/2" iron pipe in place State condition good

Dimensions above ground 1x7 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen Elm

Diameter 19 10

Bearing N 52° 15' W S 16° 45' E

Distance 23 48

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dorman J. Sutton

(Signature)

Compassman

(Title)

12-10-34 (Date)

Corner again.

Give any further facts which will aid in finding this


83 chains distant.

from which this Corner bears 558°15'E

side of trees

tree 13 inches diameter, on the S E

Metal Location Poster is on an Aspen



(Make sketch of topography near Corner)

T. LEAN R. 30W 6th EA Mer.