

U. S. Department of Agriculture

FOREST SERVICE

Posted 04

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 30W 5<sup>th</sup> Mer. Sixteenth Corner common to Sections 6, , , and



Corner consists of a Brcap iron pipe (not) in place State condition good

Dimensions above ground 1.85 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch stub W. Pine

Diameter 4" 8"

Bearing S42°W S66°15'E

Distance 23 12

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Dorman J. Sutton

(Signature)

Compassman

(Title)

12-10-34  
(Date)

Corner again.  
Give any further facts which will aid in finding this

chains distant.

from which this Corner bears


*N 60° 15' W*

side of *tree*

tree *8* inches diameter, on the

*W. Pine*

Metal Location Poster is on a



(Make sketch of topography near Corner)

*T. 143 N R. 30 W*  
*5th*  
*D-4 Mer.*