

U. S. Department of Agriculture

FOREST SERVICE

Pasted C4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 30W 5th Mer.

Sixteenth Corner common to Sections 6, and



Corner consists of a Br. cap iron pipe (not) in place State condition good

Dimensions above ground 1.13 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species E 4 m R. Oak

Diameter 4 7

Bearing S 45° W S 72° W

Distance 22 23

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dorman J. Sutton (Signature)

Corn Pressman (Title)

12-10-34 (Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears ~~SW~~ ³² ~~54 1/2~~

side of ~~tree~~

tree 4 inches diameter, on the ~~NW~~ ^{NE} SE

Metal Location Poster is on a R. Oak



(Make sketch of topography near Corner)

T. 145N R. 30W

5th

Mer.

C-4