

U. S. Department of Agriculture

FOREST SERVICE

E-7

Posted

Chippewa

NATIONAL FOREST

E7

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 30 W. 5th Mer.

1/4 Corner common to Sections

5, and 8

Corner consists of a brass capped pipe (not) in place



State condition Good

Dimensions above ground 15 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species No trees

Diameter

Bearing Open Swamp-or Meadow

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl Steadland

(Signature)


Const. Foreman

(Title)

Dec. 12, 1934

(Date)

(Make sketch of topography near Corner)



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.