

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST *E10*

CORNERS OF THE PUBLIC SURVEY

T. *143N* R. *30W* *5th* Mer. *Sixteenth*
Corner common to Sections

....., *4*, and *9*

Corner consists of a *Br cap iron pipe* (not) in place



State condition *good*

Dimensions above ground *1x12* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *No B.T.'s*

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

Dorman J. Sutton
(Signature)

Compassman
(Title)

12-13-34
(Date)


Corner again.

Give any further facts which will aid in finding this
chains distant.

from which this Corner bears *N 48° 45' W*

side of *tree*

tree *3* inches diameter, on the *NW*
Metal Location Poster is on a *Tomorack*



(Make sketch of topography near Corner)

T. 143N R. 30W 5th Mer. E-10