

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa NATIONAL FOREST B12

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 30 W. 5<sup>th</sup> Mer.

Sixteenth Corner common to Sections 4, , , and

Corner consists of a Br. cap iron (not) in place



State condition good

Dimensions above ground 1 x 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species B. Spruce

Diameter 5"

Bearing N E

Distance 6 1/2

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Dorman J. Sutton

(Signature)

Compassman

(Title)

12-20-34


(Date)

Corner again.

Give any further facts which will aid in finding this

chain distant. *0.5 1/2*

from which this Corner bears *N* side of *tree* tree *5"* inches diameter, on the *SW* Metal Location Poster is on a *B. Spruce*



(Make sketch of topography near Corner)

B-12 Mer.

5th

R. 30W.

T. 143N