

U. S. Department of Agriculture
FOREST SERVICE

A12

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143+144N R. 30W 5th Mer.

Sixteenth Corner common to Sections

33, and 4

Corner consists of a 6x cap iron pipe (not) in place



State condition good

Dimensions above ground 1 x 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|-------------|--|--|--|
| E 1/2 S4 | | | |
| BT | | | |

Species Tam. smg

Diameter 5"

Bearing S54°W

Distance 33 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Dorman J. Sutton
(Signature)

12-21-34
(Date)

Compassman
(Title)

Faint, illegible text on ruled lines.

Corner again.

Give any further facts which will aid in finding this

chains distant.


06

from which this Corner bears *S 33° W*

side of *Trees*

tree *8* inches diameter, on the *S W*

Metal Location Poster is on a *Tree*.



(Make sketch of topography near Corner)

A-12
Mer.

574

T. #574 N. R. 30 W