

U. S. Department of Agriculture

FOREST SERVICE

B13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 30W 5th Mer.

Sixteenth Corner common to Sections

4, and 3

Corner consists of a Not located (not) in place


State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Grown over	N 1/16 S 4		
	B.T.		

Species Ash AspenDiameter 14" 11"Bearing S 48° 45' E N 87° 45' WDistance 17 14Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Dorman J. Sutton
(Signature)


12-20-34
(Date)

Compassman
(Title)

The G.O. Marker was not found
It has probably been torn out and
carried away as a trail passes over
its supposed location.
An ash stake was set.

Corner again.
Give any further facts which will aid in finding this
17 chains distant.

from which this Corner bears
side of tree
tree 14 inches diameter, on the NW
Metal Location Poster is on a Ash



(Make sketch of topography near Corner)

T. 143 N R. 30 W 5th B-13 Mer.