

U. S. Department of Agriculture
FOREST SERVICE

A13

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. 30 W. 5th Mer.



Section Corner common to Sections
93, 34, 3, and 4

Corner consists of a Brace iron (not) in place
State condition good

Dimensions above ground 2x5 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Covered over	T149N R30W S34		
	B.T.		

Species Aspen Birch

Diameter 7 4

Bearing S50°W N63°E

Distance 38 50

Do you believe this to be a genuine Land Office Corner? yes.

If not, why?

Dorman J. Sutton

12-21-34
(Date)

Compassman
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears ³⁸ N50E

side of tree

tree 7 inches diameter, on the NE

Metal Location Poster is on an Aspen



(Make sketch of topography near Corner)

A-13

535

TW3 + IHHN R. 30W