

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST *Posted*

CORNERS OF THE PUBLIC SURVEY

T. *143 N* R. *30 W* *5th* Mer.

Meander Corner common to Sections
4, _____, _____, and _____



Corner consists of a *brass iron pipe (w/)* in place
State condition *good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *No B.T.'s*

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____


Dorman J. Sutton
(Signature)

12-21-34
(Date)

Compassman
(Title)

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 143N R. 30W
 5th C-12-13 Mer.