

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

*posted*

*Chippewa*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143N* R. *30W* Mer.

*MC*

Corner common to Sections

*2, 11*

and

Corner consists of a *Iron stake* (~~not~~) in place

State condition

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>2</i>		<i>11</i>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>512</i> <i>MC</i>			
<i>137</i>			

Species *Aspen*

Diameter *7*

Bearing *583W*

Distance *60*

Do you believe this to be a genuine Land Office Corner *Yes*

If not, why? \_\_\_\_\_

*A. R. Boerner*

Signature


*Estimator*

Title.

*12/3/1930*  
Date.

(Make sketch of topography near Corner.)

T. 143N R. 30W  
S 4 E-18-19 Mer.



Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.