

U. S. Department of Agriculture

FOREST SERVICE

posted

Chippewa

NATIONAL FOREST

T 19

CORNERS OF THE PUBLIC SURVEY

T. *143N.* R. *31W.* *579* Mer.

Center 1/4 Corner common to Sections
and 26



Corner consists of a *Brass Rapid Pipe (not)* in place
State condition *Good*

Dimensions above ground *5* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *N. Pine*

Diameter *1.8"*

Bearing *S. 77 1/2 W.*

40 Distance *1.87 1/2*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

J.A. Gjelhaug

(Signature)

Tech. Eng.

(Title)

12/5/39

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

I-19 Mer.

579

T. 143 N. R. 31 W.