

U. S. Department of Agriculture

FOREST SERVICE

Posted

R 19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 31 W. 5th Mer.


Quarter Corner common to Sections
23, and 26

Corner consists of a Brass Caped Pipe (not) in place
State condition Good


Dimensions above ground 7 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen W.P.M.S.

Diameter 6" 30"

Bearing N. 38 1/2 W. S 80 E

LINKS. Distance 39 3/4 16

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J.A. Gjelhaug
(Signature)

12/3/39
(Date)

Tech. Eng.
(Title)

Corner again.

Give any further facts which will aid in finding this


002 1/2 chains distant.

from which this Corner bears N 22° W.

side of Tree

tree 5 inches diameter, on the North

Metal Location Poster is on a Rock



(Make sketch of topography near Corner)

R-19
Mer.

573

T. L. A. N. R. 31 N.