

U. S. Department of Agriculture

FOREST SERVICE

Posted

R20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 31 W. 5th Mer.

Sixteenth Corner common to Sections
23, and 26

Corner consists of a Brass Capped Pipe (~~not~~) in place



State condition Good

Dimensions above ground 9 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine

Diameter 20"

Bearing N.06°W.

116 Distance 148

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. A. Gjelhaug

(Signature)

Tech. Eng.

(Title)

12/4/39

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

R-20

Mer.

5th

T. 143N R. 31W