

U. S. Department of Agriculture

FOREST SERVICE

Posted
J20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *193N* R. *31W* *5th* Mer.

East One Sixteenth Corner common to Sections
....., *11*, and *19*

Corner consists of a *Brass Capped Pipe* (not) in place



State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E 1/16 S 19	E 1/16 S 11		
BT	BT		

Species *J. Pine* *J. Pine*

Diameter *12"* *14"*

Bearing *S. 61° 30' E.* *N. 28° E.*

115 Distance *32* *13*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

J. A. Gjothang
(Signature)

11/19/39
(Date)

Tr. R. Engstrom
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer. 5-20

573

T. 143N R. 31W