

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Posted 620

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N. R. 31W. 5th Mer.

Sixteenth Corner common to Sections
 _____, _____, and 11

Corner consists of a Brass Caprol (~~rod~~) in place


State condition Fair Too high above

Dimensions above ground 29 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm

Diameter 3"

Bearing 149 1/2° W.

116 Distance 15

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. A. Gjelhaug
 (Signature)

11/26/39
 (Date)

Tech. Eng.
 (Title)

Corner again.

Give any further facts which will aid in finding this


0.15 chains distant.

from which this Corner bears S 41° E

side of Tree

tree 3 inches diameter, on the South

Metal Location Poster is on an Elm



(Make sketch of topography near Corner)

T. 143N R. 31W 5th Mer. 6-20