

U. S. Department of Agriculture  
FOREST SERVICE

Posted

J22

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 143N R. 31W 5<sup>th</sup> Mer.

Sixteenth Corner common to Sections

12, and 13.

Corner consists of a *Bx cap. iron pipe* (not) in place  
State condition *good*Dimensions above ground *1.87* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.

<i>1/6</i>			
<i>319</i>			

<i>BT</i>			
-----------	--	--	--

Species *Aspen*Diameter *10'*Bearing *S 71° W*Distance *37*Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Dorman J. Sutton*

(Signature)

*12-28-34*

(Date)

*Comptroller*

(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

..... 10..... from which this Corner bears *N 2° 30' E*

side of *Tree*

tree... *H*... inches diameter, on the *NW*

*Appan* Metal Location Poster is on a *n*



(Make sketch of topography near Corner)

*T 14 N* *R 9 W* *5th* Mer. *5-22*