

U. S. Department of Agriculture
FOREST SERVICE

Posted
H 22

Chippewa..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY


T. *143N* R. *31W* *5th* Mer.

Sixteenth Corner common to Sections
12 and

Corner consists of a *Br cap iron pipe* (not) in place
State condition *good*

Dimensions above ground *1 x 7* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Red Oak R. Oak*
Diameter *3"* *6"*
Bearing *S 52° E* *S 79° W*
Distance *21* *38*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why?

Dorman J. Sutton
(Signature)

11-28-34
(Date)


Compassman
(Title)

Corner again.

Give any further facts which will aid in finding this
..... 21 chains distant.

from which this Corner bears *N. 58° W*
side of *tree*

tree *3"* inches diameter, on the *NW*
Metal Location Poster is on a *Rock*



(Make sketch of topography near Corner)

H-22
Mer.

5th

R. 31W

T. 145N