

U. S. Department of Agriculture  
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

623

## CORNERS OF THE PUBLIC SURVEY


T. 143 N. R. 30 W. 5<sup>th</sup> Mer.Quarter Corner common to Sections  
12, andCorner consists of a Br. cap iron pipe (not) in place  
State condition good

Dimensions above ground 1x3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N Top S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.

		Metal Poster	

Species J. Pine N. Pine Aspen

Diameter 8" 17" 3"

Bearing N16°E N32°30'W S7°30'E

Distance 84 198 3 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dorman J. Sutton  
(Signature)

11-9-34

(Date)

Compassman  
(Title)

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

..... *03 1/2* from which this Corner bears *N 70° 30' W*

side of *Trees*

tree *3* inches diameter, on the *N.W.*

Metal Location Poster is on an *Aspen*



(Make sketch of topography near Corner)

6-23

Mer.

*5th*

*T. 143N R. 31W*