

U. S. Department of Agriculture
FOREST SERVICE

Posted
E13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143N.* R. *31W* *5th* Mer.

Quarter Corner common to Sections

....., *1*, and *12*.....

Corner consists of a *Breast pipe* (~~not~~) in place


State condition *good*.....

Dimensions above ground *1x8* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N *Top* S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *N. Pine* *J. Pine*

Diameter *7* *12*

Bearing *N. 55° W.* *S 9° 15' E*

Distance *10* *35*

Do you believe this to be a genuine Land Office Corner? *Yes*,

If not, why?

Dorman J. Sutton

(Signature)

Compassman

(Title)

11-14-'34
(Date)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


..... chains distant. 10

from which this Corner bears S 55° E

side of trees

tree 7 inches diameter, on the S E

Metal Location Poster is on a N Pine



(Make sketch of topography near Corner)

E-23

Mer.

5m

R. 31 W

T. 148 N