

U. S. Department of Agriculture
FOREST SERVICE

Posted

A23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144-143* R. *30 W.* Mer. *514*

1/4 Corner common to Sections
36, and *1*

Corner consists of a *Br. capped pipe 1"* (not) in place
State condition *good*

Dimensions above ground *8"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--------------------------|-------------------------|--|--|
| <i>1/4</i> <i>536</i> | <i>1/4</i> <i>51</i> | | |
| <i>B.T.</i> | <i>B.T.</i> | | |

Species *B. Gilead Birch*

Diameter *10"* *6"*

Bearing *N133°E* *S15½E*

Distance *13½* *11½*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

N. O. Goss
(Signature)

COMPASSMAN
(Title)

8/14/24
(Date)

