

U. S. Department of Agriculture

FOREST SERVICE

Postcard

Chippewa NATIONAL FOREST

N 124

CORNERS OF THE PUBLIC SURVEY

T. *143 N.* R. *31 W.* *5th* Mer.

1/16 Corner common to Sections
13, _____, and _____



Corner consists of a *brass capped pipe (not)* in place
State condition *Good*

Dimensions above ground *6"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Aspen* *W. Oak*

Diameter *7"* *6"*

Bearing *5 1/2° E* *N 85 1/2° W*

Distance *2 lks* *3 1/4 lks.*

Do you believe this to be a genuine Land Office Corner? *Yes.*

If not, why? _____

Carl Steadland

(Signature)

Const. Foreman


(Title)

Dec 10, 1934
(Date)

Handwritten notes on a series of horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

M-24