

U. S. Department of Agriculture
FOREST SERVICE

Posted
G24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143N* R. *31W* *5th* Mer.

Sixteen Corner common to Sections
12, _____, and _____



Corner consists of a *Br. cap. iron pipe* (with) in place
State condition *good*

Dimensions above ground *1x9* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Aspen*

Diameter *7"*

Bearing *S 72° 15' E*

Distance *39*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Dorman J. Sutton
(Signature)


11-9-34
(Date)

Compass man
(Title)

Lined writing area for notes.

Corner again.

Give any further facts which will aid in finding this
..... chains distant.
..... from which this Corner bears
..... side of
..... tree inches diameter, on the
..... Metal Location Poster is on a *None*



(Make sketch of topography near Corner)

T. 143N R. 31W 5th Mer. 6-24