

U. S. Department of Agriculture

FOREST SERVICE

Posted 017-18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 31 W. 5th Mer.

Meander

Corner common to Sections

22, and 23

Corner consists of a Bronze Caped pipe (~~mark~~) in place



State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SMC S23			
BT.			

Species W. Oak

Diameter 1 1/4"

Bearing N. 83° 30' E.

LKs Distance 67

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J.A. Gjelhaug

(Signature)

Tech. Eng.

(Title)

11/27/34

(Date)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.

(Make sketch of topography near Corner)

Mer.

SM

R. 31 W.

T. 143 N.

0-17 18