

U. S. Department of Agriculture  
FOREST SERVICE

*cut*  
N-3

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. ~~25~~ 25 Mer.

1/4 Corner common to Sections

18, and 19

Corner consists of a Yellow TAG (not) in place

State condition

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

*W. E. Herron*  
(Signature)


1/27/58  
(Date)

(Title)

N-3

Corner again.  
Yellow Tag on Fence  
Post on North Side of  
Road - Just Before  
ENTERING FIELD.

Metal Location Poster is on a Fence Post  
tree inches diameter, on the  
side of  
from which this Corner bears  
chains distant.  
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)