

U. S. Department of Agriculture
FOREST SERVICE

WB

L-5

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 25 W 5TH Mer.

$\frac{1}{4}$ Corner common to Sections
17, + 18, and

Corner consists of a METAL TAG (not) in place
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? NO

If not, why? THIS WAS CHAINED TO FROM $\frac{1}{4}$ COR. SOUTH AND SHOULD BE CLOSE.

W. E. HERRON
(Signature)

1/3/58
(Date)

ASST DIST FOR REG
(Title)

L-5

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

(7)

side of (Two TAGS)

tree 4 inches diameter, on the NE + SW

Metal Location Poster is on an ASH



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

L-5

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 25 W. 5^{1/2} Mer.

1/4 Corner common to Sections
17, and 18

Corner consists of a Weed stake (not) in place

State condition Badly Burned

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/4</u>		<u>1/4</u>
	<u>5</u>		<u>3</u>
	<u>17</u>		<u>18</u>
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Hanson
(Signature)

6/19/36
(Date)

(Title)

L-5


1. Name of place: *...*
 2. Name of section: *...*
 3. Name of township: *...*
 4. Name of range: *...*
 5. Name of county: *...*
 6. Name of state: *...*
 7. Name of section: *...*
 8. Name of township: *...*
 9. Name of range: *...*
 10. Name of county: *...*
 11. Name of state: *...*

Corner again! Give any further facts which will aid in finding this

chains distant. *91K*
 from which this Corner bears *N 66° E*

side of *T 100*
 tree *3* inches diameter, on the *N.E.*

Metal Location Poster is on a *A 54*



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

L-5 123

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 25 W. 5th Mer.

Corner common to Sections 14, 17, and 18

Corner consists of a Wood Stake (not) in place
State condition Badly buried

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____
Diameter _____
Bearing _____
Distance _____

No Bearing Trees

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

Hanson

(Signature)


6/19/36

(Date)

(Title)

L-5

(Make sketch of topography near Corner)



Metal Location Poster is on a *ASB*

tree *3* inches diameter, on the *N.E.*

side of *Tree.*

from which this Corner bears *N 66. E*

9 Links, ~~about~~ distant.

Give any further facts which will aid in finding this

Corner again.

T. 144 R. 25 S. 27 Mer.