

U. S. Department of Agriculture

FOREST SERVICE

P-13

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 25 W 5th Mer.

1/4 Corner common to Sections

21, and 22

Corner consists of a metal log (set) in place


State condition good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Four sets of boxes for sketching trees and recording bearings/distances.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence

S. M. Morrison

(Signature)


Forestry aid

(Title)

12-10-60

(Date)

T. 144 N. R. 25 W. Mer. 5th Mer.



Metal Location Poster is on a *cut* tree *6* inches diameter, on the *South* side of *tree* from which this Corner bears (Bearing) _____ (Distance) _____ is on Section line marker between Secs. _____ and _____ is on a _____ on the _____ (Tree, post, etc.) _____ (Name of road, trail, etc.) located chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: *Look for corner north* *South & East of log*

