

U. S. Department of Agriculture

FOREST SERVICE

Chapparron

NATIONAL FOREST

P-15

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 25 W 5th Mer.

Corner 1/4 Corner common to Sections

22, and

Corner consists of a Metal tag (170) in place

State condition good

Dimensions above ground inches.


Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence

S. M. Morrison

(Signature)


Forestry and

(Title)

12-16-60

(Date)

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Block of Block* tree *8* inches diameter, on the *East* side of *tree*

this Corner bears *0*° (Bearing) (Distance) Chains. is on

a \_\_\_\_\_ on the \_\_\_\_\_ (Tree, post, etc.) located

chains *L. W. N. S.* from Sec. Cor.;  $\frac{1}{4}$  Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again:

*Blue line marker from West of log - no river in sketch. 370*