

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST D-1

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26-27 Mer. 1-16

Corner common to Sections

....., 6, and 1

Corner consists of a tam stake (not) in place

State condition good

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S 1 16		S 1 16
--	--------------	--	--------------

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1 16 S

--

1 16 S

--

B.t

--

b.t.

--

Species Koaks snag spruce snag

Diameter 7" 9"

Bearing N 42 W S 39 E

Distance 16 ch 9 1/2 links

Do you believe this to be a genuine Land Office Corner?

If not, why?

A. Grieser
(Signature)

10/10/35
(Date)

8-7304 D-1 (Title)

U.S. Department of Agriculture

FOREST SERVICE

CORNER OF THE PUBLIC HIGHWAY

6.40 cor stake
627 48" cedar stake beside

B.T.s are badly decayed
will soon be gone

Corner again

Give any further facts which will aid in finding this

obtain distance

610E


from which this Corner bears

side of

tree 15 inches diameter, on the

610E

Metal Location Pester is on a



(Makes sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

11-19-36
 D-1

NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26-27 Mer.
1-16

Corner common to Sections 6 and 1

Corner consists of a tan. stake (not) in place
 State condition good

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.
 CARDINAL POSITION DIAGONAL POSITION

	S		S
	1		1
	16		16
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1	
16	
S	

1	
16	
S	

b. t.	
-------	--

--	--

b. t.	
-------	--

snag	
------	--

Species balsam snag

Diameter 7 in.

9 in.

Bearing N 42 W

S 39 E

Distance 16 lks.

9 1/2 lks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

A. Friesen

(Signature)

10-10-35

(Date)

(Title)

D-1

cor. stake

set 48 in. cedar stake beside G.T.O.

be gone.

B.T. are badly decayed will soon
Corner again.

Give any further facts which will aid in finding this

0.06 chains distant.

from which this Corner bears S 1 R

side of

tree inches diameter, on the

15
Metal Location Poster is on a cedar

	Sec.		Sec.
		S. 1-16 cor.	
	Sec. 6		Sec. 1

(Make sketch of topography near Corner)