

U. S. Department of Agriculture
FOREST SERVICE

123

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14th N. R. 26 W 5th Mer.

SE. 11/6

Corner common to Sections

7, _____, and _____

Corner consists of a _____ (not) in place


State condition No stake

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION






N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species T.M. T.M.

Diameter 3" 3"

Bearing N41°W S52°E

Distance 6 links 8 links

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? _____

Hanson

(Signature)

11/19/35

(Date)

(Title)

H-7

Corner again.

Give any further facts which will aid in finding this

15 LINKS ^{on the} distant.

from which this Corner bears N 71° E

side of

~~Tree~~

tree 4 inches diameter, on the N.E.

Metal Location Poster is on a T.M.

	Sec.		Sec.
	Sec.	Sec. 7	



(Make sketch of topography near Corner)

T1dd N. R 26 W. 5th Mer.